

Installation Guide

Bypass Bath Doors K-704410, K-704412, K-704414



THEBOLD LOOK OF **KOHLER**



TROUBLESHOOTING

| Symptom: Alignment | Recommended Action |
|---------------------------------------------------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------|
| 1. The top of the door panel is tilted away from the wall. | A. Remove the door panel from the top track and lower the roller that is closest to the wall. See step 18. |
| 2. The bottom of the door panel is tilted away from the wall. | A. Remove the door panel from the top track and raise the roller that is closest to the wall. See step 18. |
| 3. The door panel does not touch the bumper. | A. Determine whether door panel top or bottom is closer to the wall, and then adjust the roller closest to the wall. |
| Symptom: Water Leaks | Recommended Action |
| 1. Water leaks between panels. | A. When showering, make sure the inside panel is against the showerhead wall. |
| 2. Water leaks between the wall jamb and the door panel. | A. Adjust the door panel to line up with the wall jamb. |
| 3. Water leaks under the bottom track. | A. Check for proper silicone sealant application. See steps 23 and 24. Apply more silicone sealant in the leak location. |
| 4. Water leaks around the wall jamb area. | A. The notched wall jamb fits over the bottom track to cover any miscut or skewed cuts. Seal as directed to ensure proper watertight seal. See step 24. |
| Symptom: Operation (open/close) | Recommended Action |
| 1. The outside panel is difficult to move. | A. Ensure a gap exists between the bottom track and the door panel. If no gap exists, lower the rollers to the next hole. |
| | B. Ensure the panel is properly engaged over the bottom track. See step 17. |
| | C. Ensure the rollers are properly installed. See steps 13 and 14. |
| | D. Clean any debris in the top track groove. |
| 2. The inside panel is difficult to move. | A. Ensure a gap exists between the bottom track and the door panel. If no gap exists, lower the rollers to the next hole. |
| | B. Ensure the inside-panel guide is properly secured to the bottom frame screws. See step 19. |
| | C. Ensure the rollers are properly installed. See steps 13 and 14. |
| | D. Clean any debris in the top track groove. |
| | |

ONE-YEAR LIMITED WARRANTY

KOHLER plumbing products are warranted to be free of defects in material and workmanship for one year from date of installation.

Kohler Co. will, at its election, repair, replace or make appropriate adjustment where Kohler Co. inspection discloses any such defects occurring in normal usage within one (1) year after installation. Kohler Co. is not responsible for removal or installation costs. **Use of in-tank toilet cleaners will void the warranty.**

To obtain warranty service contact Kohler Co. either through your Dealer, Plumbing Contractor, Home Center or E-tailer, or by writing Kohler Co., Attn.: Customer Care Center, 444 Highland Drive, Kohler, WI 53044, USA, or by calling 1-800-4-KOHLER (1-800-456-4537) from within the USA and Canada, and 001-800-456-4537 from within Mexico, or visit www.kohler.com within the USA, www.ca.kohler.com from within Canada, or www.mx.kohler.com in Mexico.

IMPLIED WARRANTIES INCLUDING THAT OF MERCHANTABILITY AND FITNESS FOR A PARTICULAR PURPOSE ARE EXPRESSLY LIMITED IN DURATION TO THE DURATION OF THIS WARRANTY. KOHLER CO. AND/OR SELLER DISCLAIM ANY LIABILITY FOR SPECIAL, INCIDENTAL OR CONSEQUENTIAL DAMAGES. Some states/provinces do not allow limitations on how long an implied warranty lasts, or the exclusion or limitation of special, incidental or consequential damages, so these limitations and exclusions may not apply to you. This warranty gives you specific legal rights. You may also have other rights which vary from state/province to state/province.

This is Kohler Co.'s exclusive written warranty.