

Wiring Instructions for Single Phase Oil-Less Compressors





| 1 PHASE MOTOR WIRING DIAGRAMS |
|---------------------------------|
| FOR OL11016AC WITH BALDOR MOTOR |

| TOTAL SETTION OF WITH BALEBOTT MIGHTER | | | | | | | |
|--|---------------------|--|--|--|--|--|--|
| LOW VOLTAGE (115V) | HIGH VOLTAGE (230V) | | | | | | |
| BLUE 1 OLINE 1 | BLUE 1 ——LINE 1 | | | | | | |
| YELLOW 4 ○LINE 2 | YELLOW 4 ○ LINE 2 | | | | | | |
| WHITE 2 O | WHITE 2 O | | | | | | |
| | BROWN J O INSULATE | | | | | | |

1 PHASE MOTOR WIRING DIAGRAMS FOR OL21533AC,OL33550AC, OL42575AC, OL900V150AC WITH BALDOR MOTORS

| LOW VOLTAGE (120V) | | | HIGH VOLTAGE (230V) | | |
|------------------------------------|------------|----------------------------------|--------------------------|----------------------|-----------------|
| ORANGE RED | 3 O 8 O | LINE 1 | RED | 8 0 | LINE 1 |
| BLUE | 1 0— | | BLUE | 1 0 | |
| YELLOW | 4 Ol | LINE 2 | YELLOW | 4 0 | LINE 2 |
| WHITE BLACK | | INSULATE | ORANGE WHITE BLACK | 3 ° | INSULATE |
| BROWN | J | | BROWN | J O | INSULATE |
| OL42575 AC ONLY | | | OL42575 AC ONLY | | |
| YELLOW/WHITE — FACTORY — INSULATED | | YELLOW/WHITE — FACTORY INSULATED | | FACTORY INSULATED | |
| YELLOW/WH | IITE — | DO NOT TOUCH | YELLOW/WH | ITE — | DO NOT TOUCH |

MOTOR WIRING DIAGRAMS FOR OL11016AC AND OL21533AC 115V-1PH 60HZ ONLY



YELLOW W/BLACK (1) LINE 1

RED ————(4)

BLUE

BLACK

PURPLE _____

YELLOW 6— LINE 2

OL21533AC

YELLOW W/BLACK 1 LINE 1

BROWN -

YELLOW

ORANGE ————(4)

BROWN

WHITE

BLUE

RED


(6)— LINE 2


(5)

MOTOR WIRING DIAGRAMS FOR OL33550AC, OL435V75AC, OL610V100AC AND OL900V100AC

LOW VOLTAGE(115 V)







HIGH VOLTAGE(230 V)





