THIS DOCUMENT IS TRUE AND CORRECT AT TIME OF PUBLICATION. CONTINUED PRODUCT IMPROVEMENTS MAKE SPECIFICATIONS AND MEASUREMENTS SUBJECT TO CHANGE WITHOUT NOTICE.


NOTES:

1 | 5874PBF (ITEM 2) INCLUDES VRK5874 CARTRIDGE ASSEMBLY (ITEM 3) AND PBA6 FLANGED PUSH BUTTON (ITEM 4).

2 ENSURE TUBE IS DISCONNECTED FROM PUSH BUTTON VALVE BODY PRIOR TO REMOVAL. APPLY ONE DROP OF LOCTITE 222MS TO NOZZLE THREADS PRIOR TO FASTENING BACK ONTO BUBBLER HEAD. RE-ATTACH TUBE TO VALVE.

	ITEM	DESCRIPTION	1109.14
	1	STRAINER, WASTE ASSY	6462
	2	BUTTON, PUSH, FLANGED, PCP W/ VALVE	5874PBF
	3	VALVE REPAIR KIT	VRK5874
	4	PUSH BUTTON ASSY, FLANGED, PCP	PBA6
	5	BUBBLER HEAD ASSY, PCP	5703M
	6	PLATE, BOTTOM	PBM1109
	7	TRAP	0005982900
*	8	BACK PANEL	BP3
*	9	PLATE, MOUNTING	6700

^{*} DENOTES OPTIONAL PART.



PARTS BREAKDOWN

MODEL(S)

1455 KLEPPE LANE SPARKS, NEVADA 89431 (775) 359-4712 FAX (775) 359-7424 E-MAIL: HAWS@HAWSCO.COM

WEBSITE: WWW.HAWSCO.COM

WHEN ORDERING PARTS PLEASE SPECIFY MODEL NUMBER.

1109.14

0002076625