

Scotsman®

SCV32 - Wine Storage Unit

SCV32 – Wine Storage Unit

Wine Storage Unit



Wine Storage Unit Features

15" cabinet width, 32 bottle capacity.

Always on interior light for dramatic effect.

3 temperature zones (approx. 45°F, 50-55°F, and 60°F) for storage capacity.

Interchangable racks

Tinted, thermal-tempered reversing glass door.

Perfect match with Scotsman Ice Machines..



Warranty


- 1 years parts and labor on all components.
- 5 years parts on the compressor only.

Warranty valid in North America.

Scotsman Ice Systems
775 Corporate Woods Parkway
Vernon Hills, IL 60061

1-800-SCOTSMAN
Fax: 847-913-9844
E-mail: customer.service@scotsman-ice.com

www.scotsman-ice.com



All Models

Storage Capacity:
32 bottles

Condenser Type:
Air

Basic Electrical:
(Volts/Hz/Phase)
115/60/1

Amps:
1.0

Maximum Fuze Size:
15

Refrigerant:
R-134A

Dimensions (W x D x H):
Unit (without legs):
15" x 24.75" x 33.875"
(38.1 x 62.87 x 86.04 cm)

Shipping Carton:
18" x 26" x 38"
(45.7 x 66.0 x 96.5 cm)

Specifications

Model	Finish Cabinet / Front	Shipping Weight lb / kg
SCV32-1SC	Black / Stainless Steel	82 / 37

Accessories

Model	Description	Shipping Weight lb / kg
KRF1	Flat Rack (1)	1 / 0.45

Operating Requirements

	Minimum	Maximum
Air Temperatures	50°F (10°C)	100°F (38°C)
Water Temperatures		
Water Pressures		
Electrical Voltage	-10%	+10%

Machine requires voltage indicated on rating name plate. Failures caused by improper voltage are not considered factory defects. Scotsman products, except model SCCG50MA-1SS & SCCP5050MA-1SS, are not designed for outdoor installations nor for installation where air temperatures fall below 50°F. or exceed 100°F., nor where water temperatures fall below 40°F. or exceed 100°F. Extended periods of operation at temperatures exceeding these limitations constitute misuse under the terms of Scotsman Manufacturer's Limited Warranty, resulting in a loss of warranty coverage. Refer to owner's manual for all installation requirements. Please note: when installed in a corner, the door swing may be limited due to handle contact with the wall or cabinet face.